



Tom Barrett
Mayor

Bevan K. Baker, FACHE
Commissioner of Health

Raquel M. Filmanowicz
Health Operations Administrator

Health Department

Family and Community Health Services

web site: www.milwaukee.gov/health

Routine Food

HUBBARD & ASSOCIATES NA, INC.
KAREN'S CLUB ENTERTAINMENT
7330 N 76th St
Milwaukee, WI

7/11/2008

The following list of violations of the Wisconsin Administrative Code as adopted by reference in the Milwaukee Code of Ordinances Chapter 68, and/or other City ordinance(s) must be corrected as soon as possible but not later than the date specified. A re-inspection fee may be assessed if the violation is not corrected by that date. An inspection fee may be charged for any repeat violations.

Code Number	Description of Violation	Correct By
4-501.11	<p>There is a leak in the walk in beer cooler near the main bar area. Have the leak repaired so that the surface is smooth and cleanable and so that there is no longer a leak present.</p> <p>The ceiling of the walk in cooler is falling apart. Have the ceiling repaired. The material used for the ceiling must be smooth and cleanable.</p> <p>There are numerous damaged ceiling tiles in the basement and in the basement men's restroom. Remove all damaged ceiling tiles and replace with new tiles. Additionally, install new ceiling tiles in the entire facility where the ceiling tiles may be missing. In the area above the ice machine, install the smooth and cleanable type ceiling tiles (non-acoustic).</p> <p>The weatherstripping for the N entrance door and the patio door are damaged or missing. Install weatherstripping on the doors so that there is a tight seal and that no gaps are present.</p>	7/11/2008



Tom Barrett
Mayor

Bevan K. Baker, FACHE
Commissioner of Health

Raquel M. Filmanowicz
Health Operations Administrator

Health Department

Family and Community Health Services

web site: www.milwaukee.gov/health

Violations 6-201.11 There are tiles missing in the pool room. Replace the tiles and ensure that the old drain is properly capped and sealed. 7/11/2008

There is a large hole in the NW corner in the basement (behind the partition). Repair the hole.

5-402.11 There is no air gap for the East side ice bin waste drain in the main bar area. Have a licensed plumber properly install an air gap for the ice bin waste drain. (There must be a physical gap between the end of the drain and the top of the funnel)

****No grease production may be done in the facility until approved by the City of Milwaukee Health Department. This includes frying, cooking, and baking of any raw meats. Additionally, frying, cooking, or baking may not be done outside or anywhere on the premise until approved by the City of Milwaukee Health Department.**

****Remove all of the portable cooking equipment from the kitchen area. These items may not be used for outside cooking until approved.**

Notes:

On 7/11/2008, I served these orders upon HUBBARD & ASSOCIATES NA, INC. by leaving this report with

Inspector Signature (Inspector ID:66)

Operator Signature

Operator verified - She is not able to sign and wants me to drop it off.